



SR 200

EN

Spare parts / Accessories



No.	Description	Ordering No.
1.	PC-visor SR 366 (polycarbonate)	R01-1201
2.	Peel-offs SR 343 for PC-visor	T01-1204
3.	Glass visor SR 365 (laminated glass)	T01-1203
4.	Peel-offs SR 353 for glass visor	T01-1205
5.	Upper frame half	R01-1202
5a.	Screw x2	-
6.	Head harness, fabric	R01-1203
7.	Head harness, rubber SR 340	T01-1215
8.	Carrier strap	R01-1206
9.	Filter adapter SR 280-3	H09-0212
10.	Seal	R01-1205
11.	Gas filter (SR 217 A1, SR 218 A2, SR 315 ABE1, SR 294 ABE2, SR 297 ABEK1, SR 298 AX, SR 215 K1, SR 295 K2, SR 299-2 ABEK-Hg-P3)	-
12.	Particle filter SR 510 P3 R	H02-1312
13.	Particle filter adapter SR 611	T01-1223
14.	Pre-filter SR 221	H02-0312
15.	Steel net disc SR 336	T01-2001
16.	Pre-filter holder	R01-0605
17.	Test disc SR 322	R01-0303
18.	Pre-filter holder SR 5153	R01-0604
19.	Set of membranes	R01-1204
19a.	Exhalation x2	-
19b.	Valve covers x2	-
19c.	Inhalation x3	-
19d.	Dowels x2	-
20.	Name label SR 368	R09-0101
21.	Welding cassette SR 84	T01-1212
22.	Protective lens	R03-0507
23.	Retaining clip	R03-0518
24.	Welding lens EN 10 60x110	R03-0510
	Welding lens EN 11 60x110	R03-0511
	Welding lens EN 12 60x110	R03-0512
25.	Spectacle frame SR 341	T01-1201
26.	Small talk/Voice amplifier SR 324	T01-1217
27.	Test adapter SR 370	T01-1206
28.	Protective hood SR 64	H09-0301
29.	Protective hood short SR 345	H09-1012
	Protective hood long SR 346	H09-1112
30.	Storage box SR 344	T01-1214
31.	Storage bag 4.5 l SR 339-1	H09-0113
	Storage bag 6.3 l SR 339-2	H09-0114
32.	Cleaning tissue SR 5226. Box of 50.	H09-0401